

---

## Firmware 9.47 Notice (Aurora 1.0.20.0)

---

New features are available with the Aurora 1.0.20.0 software update. To access these features, a minimum System firmware EPROM version of 9.47 is required. Only PC1097 (dipswitch CA250, CA4500 & CA8500), PC1156 (dipswitch CA150), and future boards will support this new firmware.

New features include:

- **Block Holidays** – Adds the ability to schedule up to 32 different Holiday entries with ranges per Site
- **Reset Anti-Passback Automatic (Daily)** – Adds the ability to reset Anti-Pass Back within a Site to an UNKNOWN state, at one of 7 different selectable times
- **First Person In – Group Ranges** – Adds the ability to select a Group Range for First Person In (FPI)
- **Enhanced Lockdown – Lockdown Door Access Settings** – Adds the ability to regulate access for individual credentials during a Lockdown. This feature requires an Enhanced Lockdown license purchase

Contact Technical Support with any technical questions on these features, and Sales to place orders for EPROMS.

**dormakaba Canada Inc.**

901 Burns Street East, Whitby, Ontario, Canada L1N 0E6

1-888-539-7226 (toll free Canada/USA)

(905) 430-7226 (elsewhere)

[www.dormakaba.ca](http://www.dormakaba.ca)

**Technical Support**

Hours: 9:00 AM to 6:30 PM EST, Monday – Friday

Firmware 9.47 Notice (Aurora 1.0.20.0) – KD50030-E-0220

---