

# UL Product iQ®

## High-security Electronic Locks, Type 1

### COMPANY

#### **dormakaba USA Inc**

1525 Bull Lea Rd, Suite 100  
Lexington, KY 40511 United States

BP7011

**High Security Electronic Locks**, Model(s): 100BLP, 100BV, 100LP, 100PRO, 100R, 100V, 2000S, 2000V, 2000V Sub-Lock System, 200LP, 200R, 200V, 2100D Auditcon Locks, 400BLP, 400BV, 400LP, 400R, 400V, 500BLP, 500BV, 500LP, 500R, 500V, 50BLP, 50BV, 50C, 50G, 52LB, 52LS, 52RS, 52VS Locks, Auditcon System Locks, CE2000S, Cencon, Cencon 2000S, Cencon Motorized Deadbolt system Locks., Cencon Sublock SER121 050CLD., Cencon Swing Bolt System Locks., D50BLP, D50BV, D50S, D55S, dead bolt locks, HK50 followed by R, V, or LP, LCLX, LCMX, slide bolt, T52LA dead bolt locks., T52LB, T52LS, T52RS, T52VS, TLCL, TLCM

**High Security Electronic Locks**, Model(s): 252 vertical and round, self-powered, dead bolt & swing bolt locks with battery assist feature for time delay. Model 52 does not have the time delay or battery assist feature.

**High Security Electronic Locks**, Model(s): 52 vertical and round, self-powered, dead bolt & swing bolt locks with battery assist feature for time delay. Model 52 does not have the time delay or battery assist feature.

**High Security Electronic Locks**, Model(s): 552 vertical and round, self-powered, dead bolt & swing bolt locks with battery assist feature for time delay. Model 52 does not have the time delay or battery assist feature.

**High Security Electronic Locks**, Model(s): Auditcon 3100 Series locks with battery assist feature for time delay

**High Security Electronic Locks**, Model(s): T52 vertical and round, self-powered, dead bolt & swing bolt locks with battery assist feature for time delay. Model 52 does not have the time delay or battery assist feature.

**High Security Lock**, Model(s): Cencon CSS2 and CSD2 (with / Without Suffixes)

**Subassembly**, Model(s): 207361, 207362, 207363, 207364, 217080 or 217135, 307118, 307120

Last Updated on 2024-12-06

---

The appearance of a company's name or product in this database does not in itself assure that products so identified have been manufactured under UL Solutions' Follow - Up Service. Only those products bearing the UL Mark should be considered to be Certified and covered under UL Solutions' Follow - Up Service. Always look for the Mark on the product.

UL Solutions permits the reproduction of the material contained in Product iQ subject to the following conditions: 1. The Guide Information, Assemblies, Constructions, Designs, Systems, and/or Certifications (files) must be presented in their entirety and in a non-misleading manner, without any manipulation of the data (or drawings). 2. The statement "Reprinted from Product iQ with permission from UL Solutions" must appear adjacent to the extracted material. In addition, the reprinted material must include a copyright notice in the following format: "©2025 UL LLC."